QUICKSTART
Leica DISTO™ D3a BT

2 sec. save constant

1× recall constant

2× history (1–20)

CLEAR OFF + **2 sec.** delete history

1× → horizontal measurement permanent on

2× → horizontal measurement off

1× → **2 sec.**

1× → 2 sec.

2× → 2 sec.

MENU

MENU 2 sec.		
→ MENU	1.1	uni t
→ MENU	2.1	uni t △
→ MENU	3.1	trl
→ MENU	4.1	BEEP
→ MENU	5.1	LEVEL
→ MENU	6.1	ILLU
→ MENU	7.1	rESEt

+ or **−**
changes settings in submenu

MENU 2 sec.
saves all changed settings

CLEAR OFF
exit menu without changes

1 ON / DIST (on / measuring)
2 Smart Horizontal Mode
3 Plus (+)
4 Minus (−)
5 Area / volume
6 Storage / Memory
7 Reference
8 Functions
9 Timer
10 2nd for navgation
11 Menu / equal
12 Clear / OFF
13 Bluetooth®

- when it has to be **right**

Leica Geosystems

ON/DIST 1× → ON

CLEAR/OFF 2 sec. → OFF

ON/DIST 1×

Bluetooth® on

1× send

2 sec. send all

2nd

1× — max. +45° / max. −45°

2× → 2 sec.
A = A1+A2+A3

3×
a 1.025m / b 0.625m / a≠b / b 0.625m
a 0.625m / b 0.625m / a=b / b 0.625m

4×

5×

6×

Laser class 2 in acc. to IEC 60825-1

www.disto.com

SAP. No. 776 756a