





hedue®




WM3

Art.-Nr. D107, D109

Quick Start

www.hedue.de/manual.aspx?artnr=D107





Measuring Range:	0 - 225°
Accuracy:	±0,1°
Operating Temperature:	-10° to 50°
Storage Temperature:	-20° to 70°