





# Calibration - Kalibrierung - Calibrage

1. OFF 3 sec.



- ausschalten
- éteindre
- switch off
- desconectar
- opriiti
- spegnere
- kapatmak
- lekapcsol
- wyłączyć

2.



3. LIGHT + ON




4. ON



5.



6. ON



# hedue®

## DL1

Art.-Nr. M531

# Quick Start





### Specifications

Batteries:	2 x LR03 (AAA)
Battery life:	approx 100 hours
Measuring range:	4 x 90°
Resolution:	0,1°
Accuracy:	0,2°
Dimension:	416 x 50 x 21 mm
Weight:	330 g (incl. Battery)

