




hedue®

S301


Art.-Nr. S301

Quick Start





Calibration
Kalibrierung
Calibrage



1.



2.



3.



4.



5.



6.



Calibration
Kalibrierung
Calibrage



1.



2.



3.



4.



Specifications

Resolution: 0,5 mm
0,05°

Measuring Range: 500 mm
0 - 180°

Accuracy: ±1 mm
±0,15°

Repeatability: ±0,5 mm
±0,1°

Batteries: 2 x AAA

Working temperature: 0 - 40°

Storage temperature: -10 - 50°