

Product and Safety Information

XXL goniometer
Article No. T600



Guarantee of measurement accuracy

We have established a high quality standard in our production in order to guarantee the measuring accuracy specified in the product description. Nevertheless, we recommend that you check the measuring accuracy regularly, especially after intensive use or shocks. This way you can be sure that the device continues to work accurately. Please refer to the instructions published on our website for checking the measuring accuracy of the various measuring tools.

Small parts and choking hazard

The product contains small parts that can come loose and be swallowed. Our tools are intended for professional use and not for children. Therefore, keep the products out of the reach of children.

Sharp edges and points

This tool has sharp edges or points. Be careful to avoid cuts and abrasions. Make sure to store the tool safely when not in use to avoid accidental contact.

User note

This product is a measuring device or accessory to a measuring device and may only be used as intended by competent persons. Improper use can lead to injuries. Keep the product out of the reach of children.

Risk of crushing due to moving limbs

Pay attention to your hand and finger position when working with this tool, especially in the area of moving parts and joints. There is a risk of crushing due to unintentional folding or movement of the joints. Always hold the device firmly and avoid reaching into the folding mechanism or between joints with your fingers. Store the product in such a way that moving parts cannot come loose or open unintentionally.